ANALYSIS AND MONITORING OF RIVER WATER QUALITY IN TASIKMALAYA CITY

Nurcholis Salman^{*}

Department of Environmental Engineering, Universitas Muhammadiyah Tasikmalaya, Indonesia

Abstract

The rivers passing through the City of Tasikmalaya include the Citanduy River, the Ciloseh River, the Ciwulan River and the Cibanjaran River. While the tributaries are the Cibanjaran River which include the Cihideung/ Dalem Suba River, the Cipedes River, the Ciromban River, the Cidukuh River, the Cicacaban River, the Cibadodon River, the Cikalang River, the Tonggong Londok River, the Cibeureum River and the Cimulu River. These rivers flow and empty into the Citanduy River. The aims and objectives of this study are environmental quality monitoring activities, especially the quality of river water in the Tasikmalaya City. To find out in more detail and carefully the level of pollution that occurs, this study aims to conduct water quality monitoring so that the resulting data can determine the source of pollutants that cause deterioration of river water quality. Monitoring was conducted during the rainy season and the dry season. Based on the monitoring, it appears that the river being monitored does not meet the quality standards as a class II water body with varying status ranging from lightly polluted to heavily polluted. Parameters that do not meet quality standards include TSS, BOD, COD, nitrite, Cr6⁺, Zn, free chlorine, Total Phosphate, oil and fat, E. Coli and Total Coliform.

Keywords: Tasikmalaya City, river water pollution, Water Pollution Index

Introduction

One of the RPJN's sustainable development goals is the maintenance of environmental quality that can be used to measure the success of environmental management programs. It is an important task of a local government besides having a role in determining the formulation of policies and materials for public communication. The quality of the environment needs to be monitored to know changes from time to time (Yustiani et.al, 2016).

Part of environmental management which is the obligation of the Central, Provincial, Regency

^{*)}Corresponding Author:

E-mail: nurcholissalman@umtas.ac.id

Received: 15 December 2020 Revised: 19 February 2021 Accepted: 20 February 2021

and City governments as well as companies is environmental monitoring activities. Environmental monitoring is the periodical environmental parameter tests at predetermined locations and sampling points for a certain period (Liu et.al, 2012). This means that when environmental samples taken can represent actual conditions for the same parameters in a certain period, the monitoring data can be compared. Environmental quality data can also be used as a basis for planning, evaluation, and supervision which is very useful for decision makers, planners, program compilers, both at the central and regional levels in determining environmental policies. This is in accordance with the philosophy which states that: "No Measurement – No Data; No Data – No Information; No Information – No Management; No Management – No Policy".

Water is an environmental component that is important for human life and other living things. Water can be disastrous when it is not available in the right conditions, both in quality and quantity. One of the water bodies which is a wealth of water resources is a river. The river functions as a reservoir, storage for irrigation and raw material for drinking water for the community along its flow (Yustiani, et.al, 2017).

The river is also an easy and practical place for disposal of waste, both solid and liquid, as a result of household activities, home industry, garment, livestock, workshop, and other businesses (Roman et.al, 2016). With the disposal of various types of waste and rubbish containing various types of pollutants to water biodegradable bodies. both and nonbiodegradable, it will cause heavier loads to be received by the river. If the load received by the river exceeds the threshold set based on quality standards in Government Regulation Number 82 of 2001 concerning Management of Water Quality and Control of Water Pollution, then the river is said to be polluted, physically, chemically and biologically.

Tasikmalaya City is one of the cities in the southeastern part of West Java Province, Indonesia. The rivers flowing through the Tasikmalaya City include the Citanduy River, the Ciloseh River, the Ciwulan River and the Cibanjaran River. While the tributaries are the Cibanjaran River which include the Cihideung/ Dalem Suba River, the Cipedes River, the Ciromban River, the Cidukuh River, the Cicacaban River, the Cibadodon River, the Cikalang River, the Tonggong Londok River, the Cibeureum River and the Cimulu River. These rivers flow and empty into the Citanduy River, except for the Ciwulan River.

The aims and objectives of this study are to investigate the river water quality by means of monitoring activities. Water quality monitoring

serves to provide factual information about the condition (status) of water quality in the present, trends and predictions of past future environmental changes. The basic information generated from monitoring activities can be used as a reference for preparing environmental planning, evaluation, control and supervision, spatial planning, and location permits for businesses or activities. Monitoring data can be used as a basis for consideration, formulating policies or making decisions and evaluating environmental management policies, especially controlling water pollution.

Methodology

Water Sampling

There are several equipments used in the sampling activity:

- 1. Water sampler container/ bucket with a weight and equipped with a rope
- 2. Sample preparation tool: 6 bottles of Polyethylene Terephthalate (PET) 1.5 L.
- 3. Field testing equipment: pH meter, 2 pipette bottles, and a thermometer.

The chemical used in the sampling processes are HNO_3 p.a MERCK and H_2SO_4 p.a MERCK for sample preparation of chromium and COD parameters.

Sampling Points

There were 24 sampling points from rivers and tributaries passing through Tasikmalaya City. The sampling location were display in Table 1.

No.	River / Monitored Surface Water	Sampling Location
1.	Ciwulan Hulu	Jl. Leuwi Budah Kp. Tanjung Loka (Sasak Gantung) RT 03/03 Kec. Kawalu
2.	Ciwulan Hilir	Jl. KH. Syeh Abdul Muhyi Jembatan Sukaraja (Perbatasan Kota Tasik dengan Kabupaten Tasik) Kel. Urug Kec. Kawalu
3.	Cibangbay	Kp. Peundeuy Kel. Urug

Table 1. River Water Monitoring Locations

Hulu Kec. Kawalu 4. Cibangbay Hilir Kel. Leuwiliang-Kawalu 5. Cimulu Hulu PDAM) Kel. Cibunigeulis Kec. Bungur sari 5. Cimulu Hilir Nyangga Hurip Kel. Marga Bakti, Kec. Cibeureum 7. Cikalang Hulu Bantarsari- Bungursari 7. Cikalang Hulu Kp. Tarikolot 06/02 Kel. Margabakti 8. Cikalang Hulu Kp. Tarikolot 06/02 Kel. Margabakti 9. Cihideung Jl. Bebedilan (Depan Cuci Mobil Pusaka Jaya Motor) 10. Cihideung Jembatan 9. Citanduy Hulu Kp. Nangoh RT. 02/11 Kel. Sukamaju Kaler Kec. Indihiang 12. Citanduy Hulu Kp. Gobang Kel. Singkup Kec. Purbaratu 13. Ciloseh Bendung Bengkok Kp. Bendung Bengkok Kp. Hulu 14. Ciloseh Hilir Sukamak) 15. Cilamajang Hulu Kp. Cibeureum Kel. Sukalaksana 16. Cilamajang Hulu Kp. Cibeureum Kel. Sukalaksana 17. Ciromban Hulu Jl. Bebedahan I No. 108 – Purbaratu 19. Cibadodon Jl. Paseh - Kel. Tuguraja Kec. Cihideung 20. Cibadodon Jl. Paseh - Kel. Tuguraja Kesidence)	No.	River / Monitored Surface Water	Sampling Location
4. Hilir 5. Cimulu Hulu Kp. Gn. Kokosan (Gd. Air 7. Cimulu Hilir Nyangga Hurip Kel. Marga Bakti, Kec. Cibeureum 7. Cikalang Hulu Bantarsari- Bungursari 7. Cikalang Hulu Kp. Tarikolot 06/02 Kel. Margabakti Kec. Cibeureum 9. Cihideung JI. Bebedilan (Depan Cuci Hulu Mobil Pusaka Jaya Motor) 10. Cihideung JI. Bebedilan (Depan Cuci Hulu Kp. Nangoh RT. 02/11 11. Citanduy Hulu Kp. Nangoh RT. 02/11 11. Citanduy Hulu Kp. Nangoh RT. 02/11 11. Citanduy Hulu Kp. Sangoh RT. 02/11 12. Citanduy Hulu Kp. Gobang Kel. Singkup Kec. Purbaratu 13. Ciloseh Bendung Bengkok Kp. Hulu Bengkok Bungursari 14. Ciloseh Hilir Kp. Ganoang Sukaasih 15. Cilamajang Hulu Kp. Tanjung Loka Kec. Purbaratu 16. Ciromban Hulu Sukalaksana Kec. Purbaratu 17. Ciromban Hulu Sukalaksana Kec. Purbaratu 18. Ciromban JI. Bebedahan I No. 108 – Hilir Sukalaksana Kec. 19. Cibadodon JI. Paseh - Kel. Tuguraja Ke. Cibadodon JI. Paseh - Kel. Tuguraja Ke. Cibadodon JI. Paseh - Kel. Tug			
5. Cimulu Hulu PDAM) Kel. Cibunigeulis Kec. Bungur sari JI. Anyar RT 02/03 6. Cimulu Hilir Nyangga Hurip Kel. Marga Bakti, Kec. Cibeureum 7. Cikalang Hulu Bantarsari-Bungursari 8. Cikalang Hilir Kp. Tarikolot 06/02 Kel. 8. Cikalang Hilir Kp. Tarikolot 06/02 Kel. 9. Cihideung Hulu JI. Bebedilan (Depan Cuci Mobil Pusaka Jaya Motor) 10. Cihideung Jembatan Singkup, Hulu Morbaratu 11. Citanduy Hulu Kp. Nangoh RT. 02/11 11. Citanduy Hulu Kp. Gobang Kel. Singkup Kec. Purbaratu 12. Citanduy Hulu Kp. Ganoang Sukaasih 14. Ciloseh Hilir Sukamaju Kaler Kec. Purbaratu 15. Cilamajang Hulu Bendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu 16. Gilamajang Hulu Kp. Tanjung Loka Kec. Purbaratu 17. Ciromban Hulu Sukalaksana Kec. Purbaratu 18. Ciromban Hulu JI. Bebedahan I No. 108 – Purbaratu 19. Cibadodon JI. Paseh - Kel. Tuguraja Ke. Cibidoung Hulu Kec. Cihideung	4.		
6. Cimulu Hilir Nyangga Hurip Kel. Marga Bakti, Kec. Cibeureum 7. Cikalang Hulu Bantarsari- Bungursari 8. Cikalang Hilir Kp. Tarikolot 06/02 Kel. Margabakti Kec. Cibeureum 9. Cihideung Hulu JI. Bebedilan (Depan Cuci Mobil Pusaka Jaya Motor) 10. Cihideung Hulu Jembatan Singkup, Purbaratu 11. Citanduy Hulu Kp. Nangoh RT. 02/11 Kel. Sukamaju Kaler Kec. Indihiang 12. Citanduy Hilir Kp. Gobang Kel. Singkup Hilir 13. Ciloseh Hulu Bendung Bengkok Kp. Hulu 14. Ciloseh Hilir Sukaasih (Sukamenak) Kec. Purbaratu 15. Cilamajang Hulu Kp. Ganoang Sukaasih Sukaasih Kec. Kawalu 16. Cilomajang Hulu Kp. Cibeureum Kel. Salawu Kec. Purbaratu 17. Ciromban Hulu Kp. Cibeureum Kel. Sukalaksana Kec. Purbaratu Sukalaksana Kec. Purbaratu 19. Cibadodon Hilir J. Bebedahan I No. 108 – Hilir 20. Cibadodon Hilir J. Paseh - Kel. Tuguraja Kesidence) 21. Cidukuh J. Galunggung (Gg. Hulu 22. Cidukuh J. Golempang Kel. Hilir Sukaasih Kec.Purbaratu	5.	Cimulu Hulu	PDAM) Kel. Cibunigeulis Kec. Bungur sari
1. Hulu Kp. Tarikolot 06/02 Kel. 8. Cikalang Hilir Kp. Tarikolot 06/02 Kel. 9. Cihideung Hulu Jl. Bebedilan (Depan Cuci Mobil Pusaka Jaya Motor) 10. Cihideung Hulu Jembatan Singkup, Purbaratu 11. Citanduy Hulu Kp. Nangoh RT. 02/11 Kel. Sukamaju Kaler Kec. Indihiang 12. Citanduy Hilir Kp. Gobang Kel. Singkup Kec. Purbaratu 13. Ciloseh Hulu Bendung Bengkok Kp. Bengkok Bungursari 14. Ciloseh Hilir (Sukamenak) Kec. Purbaratu 15. Cilamajang Hulu Bendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu Bendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu 16. Cilamajang Hulu Kp. Cibeureum Kel. Sukalaksana Hulu Sukalaksana Kec. Purbaratu 18. Ciromban Hulu Jl. Bebedahan I No. 108 – Hilir 19. Cibadodon Jl. Paseh - Kel. Tuguraja Hulu 20. Cibadodon Jl. Paseh - Kel. Tuguraja Hulu 21. Cidukuh Jl. Galunggung (Gg. Hulu 22. Cidukuh Jl. Golempang Kel. Hilir 23. Cinutut Hulu <t< td=""><td>6.</td><td>Cimulu Hilir</td><td>Nyangga Hurip Kel. Marga</td></t<>	6.	Cimulu Hilir	Nyangga Hurip Kel. Marga
8. Chaining Hilir Margabakti Cibeureum Kec. Cibeureum 9. Cihideung Hulu Jl. Bebedilan (Depan Cuci Mobil Pusaka Jaya Motor) 10. Cihideung Hilir Jembatan Singkup, Purbaratu 11. Cihideung Hilir Jembatan Singkup, Singkup, Singkup, Hulu 12. Citanduy Hilir Kp. Nangoh RT. 02/11 Kel. Sukamaju Kaler Kec. Indihiang 12. Citanduy Hilir Kp. Gobang Kel. Singkup Kec. Purbaratu 13. Ciloseh Hulu Bendung Bengkok Kp. Bengkok Bungursari 14. Ciloseh Hilir Sukaasih (Sukamenak) Kec. Purbaratu 15. Cilamajang Hulu Bendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu 16. Cilamajang Hulu Kp. Cibeureum Kel. Sukalaksana Kec. Purbaratu 17. Ciromban Hulu Jl. Bebedahan I No. 108 – Hilir Purbaratu 18. Ciromban Hilir Jl. Paseh - Kel. Tuguraja Kec. Cihideung Leuwi Munding (Belakang Perum Grand Laswi Residence) 20. Cibadodon Hilir Jl. Galunggung (Gg. Hulu Mesjid Baitul Mulya) 22. Cidukuh Jl. Jl. Golempang Kel. Hilir Jl. Lukmanul Hakim 23. Cinutut Hulu (depan ruko A9) Ke	7.	-	Bantarsari- Bungursari
9.HuluMobil Pusaka Jaya Motor)10.CihideungJembatanSingkup,11.CitanduyKp.NangohRT.02/1111.CitanduyKp.SukamajuKalerKec.11.IndihiangItaliangItaliangItaliang12.CitanduyKp.GobangKel.Singkup13.CilosehBendungBengkokKp.13.CilosehBendungBengkokKp.14.Ciloseh Hilir(Sukamenak)Kec.15.Cilamajang HuluBendungCilamajang Kp. Gn.Lingga-Kel.16.Cilamajang HuluKp.Cibeuti Kec.Kec.17.Ciromban HuluJ.Bebedahan I No.108 – Hulir18.Ciromban HilirJ.Bebedahan I No.108 – Hulu19.Cibadodon HilirLeuwi Munding (Belakang Perum Grand Laswi Residence)Italiang Residence)21.Cidukuh HilirJ.Golempang Kel.Kel.22.Cidukuh HilirJ.Golempang Sel.Kel.23.Cinutut Hulu(depan ruko A9)Kel.Tugu	8.	-	Margabakti Kec.
10. Hilir Purbaratu 11. Citanduy Hulu Kp. Nangoh RT. 02/11 Kel. Sukamaju Kaler Kec. Indihiang 12. Citanduy Hilir Kp. Gobang Kel. Singkup Kec. Purbaratu 13. Ciloseh Hulu Bendung Bengkok Kp. Bengkok Bungursari 14. Ciloseh Hilir Kp. Ganoang Sukaasih (Sukamenak) 15. Cilamajang Hulu Bendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu 16. Cilamajang Hulu Kp. Cibeureum Kel. Sukalaksana Hulu 17. Ciromban Hulu Kp. Cibeureum Kel. Sukalaksana Hulu 18. Ciromban Hilir Jl. Bebedahan I No. 108 – Hilir 19. Cibadodon Hulu Leuwi Munding (Belakang Perum Grand Laswi Residence) 21. Cidukuh Hilir Jl. Galunggung (Gg. Hulu 22. Cidukuh Hilir Jl. Golempang Kel. Hilir 23. Cinutut Hulu Jl. Lukmanul Hakim	9.		
11.Chanduy HuluKel. Sukamaju Kaler Kec. Indihiang12.Citanduy HilirKp. Gobang Kel. Singkup Kec. Purbaratu13.Ciloseh HuluBendung Bengkok Kp.13.Ciloseh HuluBendung Bengkok Kp.14.Ciloseh HilirKp. Ganoang Sukaasih14.Ciloseh Hilir(Sukamenak) Kec. Purbaratu15.Cilamajang HuluBendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu16.Cilamajang HilirKp. Tanjung Loka Kec. Sukalaksana Hulu17.Ciromban HilirKp. Cibeureum Sukalaksana Purbaratu18.Ciromban HilirJl. Bebedahan I No. 108 – Purbaratu19.Cibadodon HilirJl. Paseh - Kel. Tuguraja Residence)20.Cibadodon HilirLeuwi Munding (Belakang Perum Grand Laswi Residence)21.Cidukuh HuluJl. Galunggung Mesjid Baitul Mulya)22.Cidukuh HilirJl. Golempang Sukaasih Kec.Purbaratu23.Cinutut Hulu(depan ruko A9) Kel. Tugu	10.		81,
12.HilirKec. Purbaratu13.CilosehBendung Bengkok Kp.14.Ciloseh HilirKp. Ganoang Sukaasih14.Ciloseh Hilir(Sukamenak)15.Cilamajang HuluBendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu16.Cilamajang HilirKp. Tanjung Loka Kec. Purbaratu17.Ciromban HuluKp. Cibeureum Kel. Sukalaksana Hulu18.Ciromban HilirJl. Bebedahan I No. 108 – Purbaratu19.Cibadodon HilirJl. Paseh - Kel. Tuguraja Residence)20.Cibadodon HilirLeuwi Munding (Belakang Perum Grand Laswi Residence)21.Cidukuh HuluJl. Galunggung (Gg. Hulu22.Cidukuh HilirJl. Golempang Sukaasih Kec.Purbaratu23.Cinutut Hulu(depan ruko A9) Kel. Tugu	11.		Kel. Sukamaju Kaler Kec.
13.HuluBengkok Bungursari14.Ciloseh HilirKp. GanoangSukaasih14.Ciloseh Hilir(Sukamenak)Kec.PurbaratuPurbaratu15.Cilamajang HuluBendung Cilamajang Kp. Gn. Lingga-Kel. Cibeuti Kec. Kawalu16.Cilamajang HilirKp. Tanjung Loka Kec. Salawu17.Ciromban HuluKp. Cibeureum Sukalaksana Hulu18.Ciromban HilirJl. Bebedahan I No. 108 – Purbaratu19.Cibadodon Hulu HilirJl. Paseh - Kel. Tuguraja Residence)20.Cibadodon Hilir HuluLeuwi Munding (Belakang Perum Grand Laswi Residence)21.Cidukuh HuluJl. Galunggung Mesjid Baitul Mulya)22.Cidukuh HilirJl. Golempang Sukaasih Kec.Purbaratu23.Cinutut Hulu(depan ruko A9) Kel. Tugu	12.		
14. Ciloseh Hilir (Sukamenak) Kec. Purbaratu Purbaratu Bendung Cilamajang Kp. 15. Cilamajang Hulu Bendung Cilamajang Kp. 16. Cilamajang Hilir Salawu 17. Ciromban Hulu Kp. Cibeureum Kel. 18. Ciromban Hilir Jl. Bebedahan I No. 108 – Purbaratu 19. Cibadodon Hilir Leuwi Munding (Belakang Perum Grand Laswi Residence) 20. Cidukuh Hilir Jl. Galunggung (Gg. Hulu Mesjid Baitul Mulya) 22. Cidukuh Jl. Golempang Kel. 33. Cinutut Hulu (depan ruko A9) Kel. Tugu	13.		
15.Chamajang HuluGn. Kec.Lingga-Kel.Cibeuti Kec.16.Cilamajang HilirKp.Tanjung Salawu16.Ciromban HuluKp.Cibeureum Sukalaksana Purbaratu17.Ciromban HuluKp.Cibeureum Sukalaksana Purbaratu18.Ciromban HilirJl.Bebedahan I No.19.Cibadodon HuluJl.Paseh - Kel.Tuguraja Residence)20.Cibadodon HilirLeuwi Munding (Belakang Perum Grand Laswi Residence)21.Cidukuh HuluJl.Galunggung Gg.22.Cidukuh HilirJl.Golempang Sukaasih Kec.Purbaratu Jl.23.Cinutut Hulu(depan ruko A9) Kel.Tugu	14.	Ciloseh Hilir	(Sukamenak) Kec.
16. Hilir Salawu 17. Ciromban Hulu Kp. Cibeureum Kel. 17. Ciromban Hulu Kp. Cibeureum Kel. 18. Ciromban Hilir Jl. Bebedahan I No. 108 – 19. Cibadodon Hulu Jl. Paseh - Kel. Tuguraja Kec. 20. Cibadodon Hilir Leuwi Munding (Belakang Perum Grand Laswi Residence) 21. Cidukuh Jl. Galunggung (Gg. 411 Sukaasih Kec.Purbaratu Jl. Golempang Kel. 22. Cidukuh Jl. Golempang Kel. 23. Cinutut Hulu (depan ruko A9) Kel. Tugu	15.		Gn. Lingga-Kel. Cibeuti
17. Ciromban Hulu Sukalaksana Purbaratu Kec. 18. Ciromban Hilir Jl. Bebedahan I No. 108 – Purbaratu 19. Cibadodon Hulu Jl. Paseh - Kel. Tuguraja Kec. Cihideung 20. Cibadodon Hilir Leuwi Munding (Belakang Perum Grand Laswi Residence) 21. Cidukuh Hulu Jl. Galunggung (Gg. Mesjid Baitul Mulya) 22. Cidukuh Hilir Jl. Golempang Sukaasih Kec.Purbaratu 23. Cinutut Hulu (depan ruko A9) Kel. Tugu	16.		1 5 6
18. Hilir Purbaratu 19. Cibadodon Jl. Paseh - Kel. Tuguraja Hulu Kec. Cihideung 20. Cibadodon Hilir Leuwi Munding (Belakang Perum Grand Laswi Residence) 21. Cidukuh Hulu Mesjid Baitul Mulya) 22. Cidukuh Hilir Sukaasih Kec.Purbaratu Jl. Lukmanul 23. Cinutut Hulu (depan ruko A9) Kel. Tugu	17.		Sukalaksana Kec.
19. Hulu Kec. Cihideung 20. Cibadodon Hilir Leuwi Munding (Belakang Perum Grand Laswi Residence) 21. Cidukuh Hulu Jl. Galunggung (Gg. Mesjid Baitul Mulya) 22. Cidukuh Hilir Jl. Golempang Sukaasih Kec.Purbaratu 23. Cinutut Hulu (depan ruko A9) Kel. Tugu	18.		
20.Cibadodon HilirPerum Residence)21.Cidukuh HuluJl.Galunggung (Gg. Mesjid Baitul Mulya)22.Cidukuh HilirJl.Golempang Sukaasih Kec.Purbaratu Jl.23.Cinutut Hulu (depan ruko A9) Kel. Tugu	19.		
21.HuluMesjid Baitul Mulya)22.CidukuhJl.GolempangKel.HilirSukaasih Kec.PurbaratuJl.LukmanulHakim23.Cinutut Hulu(depan ruko A9) Kel. Tugu	20.	Hilir	Perum Grand Laswi
22.HilirSukaasih Kec.PurbaratuJl.LukmanulHakim23.Cinutut Hulu(depan ruko A9) Kel. Tugu	21.		
23. Cinutut Hulu (depan ruko A9) Kel. Tugu	22.		1 0
jaya Kec. Cinideung	23.	Cinutut Hulu	
24. Cinutut Hilir Jl. Taman Harapan	24.	Cinutut Hilir	

No.	River / Monitored Surface Water	Sampling Location
		(Jembatan Cibadodon)

Referring to the Decree of the State Minister for Environment Number 115 of 2003 the concerning Guidelines for Determining the Status of Water Quality, one of the methods used to determine the quality status of river water is the pollution indexing method. The pollution index is an index related to pollution compounds used to determine the level of pollution relative to the permissible water quality parameters (Nemerow 1974 in Kepmen-LH Number 115 of 2003). Management of water quality on the basis of the Pollution Index (IP) can provide input in decision making in order to assess the quality of the waters for a designation and take action to improve the quality if there is a decrease in quality due to the presence of pollutants. Water quality designation (i) (Appendix 3) and Ci states the concentration of water quality parameters (i) obtained from the analysis results, then Pij is the Pollution Index for the allocation (j) which is a function of Ci / Lij. Pij is determined by:

- 1. Choosing parameters if the parameter price is low, the water quality will improve.
- 2. Select a quality standard parameter concentration that does not have a range.
- 3. Calculating the Ci / Lij price for each parameter at each sampling location.
- 4. If a decreasing concentration value indicates an increased level of pollution (for example DO), then the maximum value of Cim is determined (for example for DO, then Cim is the saturated DO value). In this case the measured Ci / Lij value is replaced by the calculated Ci / Lij value, namely:

$$(Ci/Lij) new = \frac{Cim - Ci (measurement)}{Cim - Lij}$$
(1)

If the Lij quality standard value has a range,

- for
$$C_i \le L_{ij}$$
 average
(Ci/Lij) baru =
$$\frac{[Ci - (Lij)average]}{[(Lij)min - (Lij)average]}$$
(2)

- for
$$C_i > L_{ij}$$
 average
(Ci/Lij) baru =
$$\frac{[Ci - (Lij)average]}{[(Lij)max - (Lij)average]}$$
(3)

If two values (Ci/Lij) are adjacent to the reference value 1.0. Suppose (C1 / L1j) = 0.9 and (C2/L2j) = 1.1 or a very large difference, for example (C3/L3j) = 5.0 and (C4/L4j) = 10.0.

In this example the extent of damage to water bodies is difficult to determine. The way to overcome this is:

- Use of the value (Ci/Lij) of the results measurement if this value <1.0, then the value

$$(C_i/L_{ij})_{new} = (C_i/L_{ij})_{measurement}$$
(4)

- If the result of (Ci/Lij) measurement> 1.0 then the new (Ci/Lij) value can be obtained from:

(Ci/Lij)new = 1,0 + P.log(Ci/Lij)measurement

P is a constant and its value is determined independently and adjusted to the results of environmental observations and or the desired requirements for a designation (usually the value 5).

Determine the average and maximum values of the overall Ci/Lij ((C /Lij) R and (Ci/Lij) M). So that the value of the Pollution Index can be known from the equation:

$$Pij = \sqrt{\frac{(Ci/Lij)M^2 + (Ci/Lij)R^2}{2}}$$
(5)

From the results of the calculation of the Pollution Index value, the value or score describes the condition of the water quality according to the criteria in the following table.

 Table 2. Determination of water quality status

 based on the Pollution Index

Score	Criteria
$0.0 \leq P_{Ij} \leq 1.0$	Good
$1.0 < P_{Ij} \le 5.0$	Lightly polluted
$5.0 < P_{Ij} \leq 10$	Moderately polluted
$P_{Ij} > 10$	Heavily polluted

The result of sampling and laboratory analysis of river water quality in Tasikmalaya City is as in Table 3. Based on the results of monitoring conducted at several monitoring locations during two monitoring periods, assuming the rainy season and dry season, it appears that the river being monitored does not meet the quality standards as a class II water body with varying status starting from lightly polluted, moderately polluted to heavily polluted (Table 4). Parameters that do not meet quality standards include TSS, BOD, COD, nitrite, Cr6⁺ metal, Zn metal, free chloride, Total Phosphate, oil and grease, E. Coli and Total Coliform.

The river in Tasikmalaya City is generally used by residents for agricultural irrigation. On the other hand, water resources are also used as water bodies that receive waste from industrial or domestic activities that have the potential to reduce the quality of these water bodies. Water body pollution can occur due to industrial waste, household/ domestic waste and agricultural waste.

Based on the source, pollution can be grouped into 3 (three) namely pollution that comes from households (domestic), industrial waste from companies, and agricultural / plantation waste. Various kinds of pollutant sources indicate that the concentration of pollutants varies widely; this is because the sources of wastewater also vary so that the time factor and the sampling method greatly affect the concentration.

No	River Name	Monitoring Point	Date (mm/dd/yyyy)	Temp (°C)	рН	TDS (mg/L)	TSS (mg/L)	BOD (mg/L)	COD (mg/L)	NO ₂ (mg/L)	NO ₃ (mg/L)	Free Chloride (mg/L)	TP (mg/L)	Oil & Grease (mg/L)	Fecal Coliform (/100 ml)	Total Coliform (/100 ml)
1	Circultur Herbe	Jl. Leuwi Budah	2/24/2019	27.0	7.9	112	38	3	22	0.01	0.4	0.12	0.3	6	3,200	14,000
1	Ciwulan Hulu	Kec. Kawalu	8/14/2019	26.5	7.5	102	24	3	20	0.01	0.3	0.1	0.2	4	2,400	10,000
2	C' 1 U'''	Jl Syekh Abdul	2/24/2019	27.1	8.3	102	38	3	22	0.01	0.1	0.1	0.25	8	1,600	12,100
2	Ciwulan Hilir	Muhyi (Jembatan Sukaraja	8/14/2019	27.0	8.1	96	26	3	18	0.01	0.1	0.1	0.2	6	1,200	10,000
2		Kp. Peundeuy	2/20/2019	25.1	8.5	169	14	1	9	0.02	0.7	0.08	0.11	48	300	1,900
3	Cibangbay Hulu	Kel. Urug Kec. Kawalu	8/22/2019	25.0	8.1	148	12	1	8	0.002	0.5	0.05	0.11	24	200	1,400
4	Cibon aboy Uilin	Kel. Leuwiliang	2/20/2019	25.5	8.2	236	4	1	9	0.012	0.3	0.06	0.42	4	1,700	10,800
4	Cibangbay Hilir	Kec. Kawalu	8/22/2019	25.6	8.1	212	4	1	5	0.012	0.2	0.06	0.42	3	1,200	9,600
5	Cimulu Hulu	Kp. Gn. Kokosan	5/8/2019	28.3	8.3	773	8	1.6	4	0.011	0.8	0.01	1.4	11	2,300	18,800
3		Kec. Bungursari	10/30/2019	28.3	8.1	680	6	2	4	0.011	0.8	0.01	1.2	9	2,000	16,000
6	Cimulu Hilir	Nyangga Hurip Kel. Margabakti Kec. Cibeureum	5/8/2019	37.9	7.4	111	10	2	5	0.016	0.6	0.16	0.19	76	55,100	60,500
6	Cimulu Hilir		10/30/2019	27.0	7.5	96	8	2	4	0.014	0.4	0.1	0.1	56	35,100	55,100
7	Cikalana Uulu	Kel. Bantarsari - Kec. Bungursari	2/10/2019	26.5	8.3	28	4	4	15	0.001	0.3	0.05	1.07	42	1000	5000
/	Cikalang Hulu		9/8/2019	27.0	8.1	24	4	4	12	0.001	0.2	0.05	0.6	32	600	1,25x10 ⁴
8	Cikalang Hilir	Kel. Margabakti Kec. Cibeureum	2/10/2019	27.6	8.1	32	2	10	16.5	0.008	0.7	0.08	0.19	20	1000	5000
0			9/8/2019	28.0	7.9	32	28	8	15	0.008	0.6	0.05	0.8	16	4,200	8000
9	Cihideung Hulu	u Jl. Bebedilan	5/10/2019	26.8	7.6	196	20	9	23	0.001	0.1	0.01	1.54	103	62,100	430,000
2	Clinideulig Hulu		11/1/2019	27.0	7.8	182	14	7	18	0.001	0.1	0.01	1.24	84	46,200	240,000
10	Cibidana a Ulia	Jembatan	5/10/2019	28.2	7.4	117	48	2.18	4	0.24	1.2	0.05	0.78	31	7,100	38,500
10	Cihideung Hilir	Singkup Kec. Purbaratu	11/1/2019	28.4	7.5	102	34	2	4	0.12	0.8	0.05	0.56	22	4,600	24,500
	1 Citanduy Hulu	Jl. Letjen Ibrahim Adjie Kec. Indihiang	2/28/2019	25.0	8.5	92	14	3.5	26	0.013	0.4	0.05	0.22	7	1,100	7,700
11			8/18/2019	26	8.1	76	8	3	20	0.013	0.5	0.03	0.18	5	900	6,200
		Kp. Gobang Kel.	2/28/2019	27.4	8.2	101	42	2	6	0.007	0.2	0.04	0.33	12	200	1,100
12	Citanduy Hilir	Singkup Kec. Purbaratu	8/18/2019	28.0	7.9	98	36	2	5	0.006	0.2	0.03	0.2	8	100	900
		Bendung	2/27/2019	27.7	8.6	102	2	17	7	0.005	0.6	0.09	0.48	6	700	32,000
13	3 Ciloseh Hulu	ulu Bengkok Kp. Bengkok Kec.	9/7/2019	28.1	7.8	96	2	6	15	0.003	0.5	0.07	0.32	4	600	28,000

Table 3 Results of River Monitoring in the City of Tasikmalaya

No	River Name	Monitoring Point	Date (mm/dd/yyyy)	Temp (°C)	рН	TDS (mg/L)	TSS (mg/L)	BOD (mg/L)	COD (mg/L)	NO ₂ (mg/L)	NO ₃ (mg/L)	Free Chloride (mg/L)	TP (mg/L)	Oil & Grease (mg/L)	Fecal Coliform (/100 ml)	Total Coliform (/100 ml)
		Bungursari														
		Kp. Ganoang	2/27/2019	28.1	8.2	56	6	18.5	22	0.026	0.8	0.01	1.07	14	1,300	21,800
14	Ciloseh Hilir	Sukaasih (Sukamenak) Kec. Purbaratu	9/7/2019	28.5	7.6	48	4	14	20	0.001	0.6	0.01	0.8	12	1,100	18,000
		Kp. Gn. Lingga	2/6/2019	24.0	8.0	146	76	5	7	0.034	0.2	0.04	1.25	6	1,200	5,600
15	Cilamajang Hulu	Kel. Cibeuti Kec. Kawalu	8/15/2019	25.0	7.6	128	62	4	6	0.03	0.2	0.03	0.8	5	1,100	4,800
		Kp. Tanjung	2/6/2019	25.2	6.8	138	76	4	23	0.038	0.7	0.09	1.49	10	900	3,600
16	Cilamajang Hilir	Loka Kec. Kawalu	8/15/2019	25.0	6.5	124	56	3	22	0.04	0.6	0.06	1.2	8	700	2,800
		Kp. Cibeureum	5/15/2019	27.1	7.7	144	202	15	38	0.005	0.9	0.03	0.39	31	500	2,900
17	Ciromban Hulu	Hulu Kel. Sukalaksana Kec. Purbaratu	11/3/2019	28.0	7.4	124	186	12	28	0.005	0.8	0.03	0.33	24	400	2,400
		Jl. Bebedahan I	5/15/2019	27.6	7.3	180	4	6	15	0.018	0.3	0.02	1.73	10	1000	12,700
18	Ciromban Hilir	No. 108 Kec. Purbaratu	11/3/2019	27.0	7.5	140	4	4	10	0.016	0.3	0.01	1.56	8	600	10,000
		Jl. Paseh - Kel.	2/3/2019	29.1	8.1	452	66	77.5	122	0.021	1.2	0.07	3.75	120	30,000	330,000
19	Cibadodon Hulu	Tuguraja Kec. Cihideung	9/14/2019	28	7.7	348	56	64.2	112	0.01	0.8	0.06	2.76	82	10,000	220,000
		Leuwi Munding	2/3/2019	28.8	7.8	160	30	12	30	0.012	0.7	0.1	12	83	10,000	90,000
20	Cibadodon Hilir	(Belakang Perum Grand Laswi Residence)	9/14/2019	28	7.6	140	24	10	26	0.01	0.5	0.05	8	64	7,000	60,000
		Jl. Galungggung	5/9/2019	26.4	7.4	103	92	29	73	0.025	0.3	0.02	0.91	8	8,400	9,000
21	Cidukuh Hulu	(Gg. Mesjid Baitul Mulya)	10/31/2019	26.0	7.5	84	64	18	36	0.01	0.2	0.02	0.4	6	5,400	7,000
		Jl. Gelompang	5/9/2019	28.0	7.7	106	202	5.6	14	0.038	0.7	0.02	0.41	25	6,400	43,500
22	Cidukuh Hilir	Kel. Sukaasih Kec. Purbaratu	10/31/2019	27.5	7.4	92	124	5	12	0.02	0.6	0.02	0.3	18	1,800	38,100
		Jl. Lukmanul	5/15/2019	26.8	8.4	140	38	2.8	7	0.08	0.08	0.02	0.88	0.88	2,600	20,400
23	Cinutut Hulu	Hakim Kel. Tugujaya Kec. Cihideung	11/2/2019	26.5	8.1	128	26	2.4	6	0.06	0.6	0.02	0.6	0.6	2,000	18,200
		Jl. Taman	5/15/2019	28.4	7.5	149	36	6	16	0.051	0.4	0.02	1.53	1.53	31,700	54,700
24	Cinutut Hilir	Harapan (Jembatan Cibadodon)	11/2/2019	27.5	7.6	132	28	б	16	0.051	0.4	0.02	1.24	1.24	29,100	48,200

No	River Name	Period I Water	Period II Water	Parameters that Exceed Quality Standards
110	Mver Name	Quality Status	Quality Status	Tarameters that Exectly Quanty Standards
1	Ciwulan Hulu	Heavily polluted	Heavily polluted	Free Chlorine, Fecal Coliform, Total Coliform
2	Ciwulan Hilir	Moderately polluted	Moderately polluted	Free Chlorine, Total Coliform
3	Cibangbay Hulu	Lightly polluted	Lightly polluted	Free Chlorine
4	Cibangbay Hilir	Moderately polluted	Moderately polluted	Free Chlorine, Total Coliform
5	Cimulu Hulu	Heavily polluted	Heavily polluted	Total Phospat, Fecal Coliform, Total Coliform
6	Cimulu Hilir	Heavily polluted	Heavily polluted	Free Chlorine, Fecal Coliform, Total Coliform
7	Cikalang Hulu	Moderately polluted	Moderately polluted	Free Chlorine, Total Phosphate
8	Cikalang Hilir	Moderately polluted	Moderately polluted	BOD, Free Chlorine, Fecal Coliform
9	Cihideung Hulu	Heavily polluted	Heavily polluted	BOD, Total Phosphate, Fecal Coliform, Total Coliform
10	Cihideung Hilir	Heavily polluted	Heavily polluted	Free Chlorine, Fecal Coliform, Total Coliform
11	Citanduy Hulu	Lightly polluted	Lightly polluted	Free Chlorine
12	Citanduy Hilir	Lightly polluted	Lightly polluted	Free Chlorine
13	Ciloseh Hulu	Heavily polluted	Heavily polluted	BOD, Free Chlorine, Total Coliform
14	Ciloseh Hilir	Moderately polluted	Moderately polluted	BOD, Total Phosphate, Total Coliform
15	Cilamajang Hulu	Moderately polluted	Moderately polluted	Free Chlorine, Total Phosphate
16	Cilamajang Hilir	Moderately polluted	Moderately polluted	Free Chlorine, Total Phosphate
17	Ciromban Hulu	Lightly polluted	Lightly polluted	BOD
18	Ciromban Hilir	Moderately polluted	Moderately polluted	Total Phosphate, Total Coliform
19	Cibadodon Hulu	Heavily polluted	Heavily polluted	BOD, COD, Free Chlorine, Total Phosphate, Fecal Coliform, Total Coliform
20	Cibadodon Hilir	Heavily polluted	Heavily polluted	BOD, Free Chlorine, Total Phosphate, Fecal Coliform, Total Coliform
21	Cidukuh Hulu	Heavily polluted	Heavily polluted	BOD, COD, Fecal Coliform
22	Cidukuh Hilir	Moderately polluted	Moderately polluted	Fecal Coliform, Total Coliform
23	Cinutut Hulu	Moderately polluted	Moderately polluted	Fecal Coliform, Total Coliform
24	Cinutut Hilir	Heavily polluted	Heavily polluted	Total Phosphate, Fecal Coliform, Total Coliform

Table 4 Status of River Water Quality in Tasik Malaya City

Visually the condition several water samples were seen turbid. Based on the results of the calculation of the water quality status of several rivers, there are rivers that have TSS values above the required Class II water quality standards. This is because the condition of the river water has begun to change its function due to the many activities that occur along the river so that it will affect the physical condition of the water which is formerly clearly visible from the total amount of suspended solids in the river.

Other river water parameters that exceed Class II Water Quality standards are COD levels at several monitoring points. This COD parameter is a very important parameter because this parameter is also an indicator of water pollution. COD is the amount of oxygen needed to oxidize organic substances in rivers by utilizing potassium dichromate oxidizer as a source of oxygen. The COD figure is a measure of water pollution by organic substances which can naturally be oxidized through biological processes and can reduce dissolved oxygen in rivers. The high COD parameter can be caused by industrial waste or domestic waste (Ramawati et.al, 2013). On the other hand, water that is not polluted has a low COD value.

Another river water parameter that also exceeds Class II Water Quality standards is free chloride found in several rivers. The presence of free chloride can be caused by natural conditions. Naturally, the presence of chloride in rivers is very large. Excessive concentrations of free chloride will certainly be harmful to health if the water is used as a source of drinking water.

Conclusion

Based on the monitoring, laboratory analysis and data processing, it can be concluded as follows:

• River status are varied from lightly polluted, moderately polluted to heavily polluted

- The index shows that river water status was similar between two periods of monitoring.
- Parameters that do not meet quality standards include TSS, BOD, COD, nitrite, Cr6⁺, Zn, free chlorine, Total Phosphate, oil and fat, E. Coli and Total Coliform.

References

- Liu, Y., Zheng, B.H., Fu, Q., Wang, L.J., Wang, M. (2012). The Selection of Monitoring Indicators for River Water Quality Assessment. *Procedia Environmental Sciences*, Vol. 13: 129-139.
- Ministry of Environmental of Republic of Indonesian Kepmen-LH Number 115 of 2003.
- Rahmawati, Chadijah, St., Ilyas, A. Analisa Penurunan Kadar COD dan BOD Limbah Cair Laboratorium Biokimia UIN Makasar menggunakan Fly Ash Batubara. Al-Kimia, Vol 1(1): 64-75.
- Roman, M., Duan, F.K., Suwari. (2016). Kontribusi Limbah Domestik Penduduk di Sekitar Sungai Biknoi terhadap Kualitas Air Bendungan Biknoi sebagai Sumber Baku Air Minum Serta Upaya Penanganannya. *Jurnal Bumi Lestari*, Vol. 16(2): 155-162.
- Yustiani, Y.M., Lidya, L. (2016). Towards an Information System of Modeling and Monitoring of Cikapundung River, Bandung, Indonesia. *Procedia Engineering*, 154: 353-360.
- Yustiani, Y.M., Lidya, L., Matsumoto, T., Rachman, I., Komariah, I. Formulation of the Integrated Information System of River Water Quality in the Cikapundung River Bandung, Indonesia. *International Journal* of Engineering and Technology, Vol. 9(1): 137-142